

Transition taper formula:

$L = S \times \frac{1}{2}W$ for speeds of 45 or more.

$L = \frac{1/2WS^2}{60}$ for speeds of 40 or less.

L = Length of transition taper
W = Width of offset
S = Speed limit

All striping to be Thermoplastic.
Conflicting markings are to be obliterated.





TYPICAL SECTION

600-23

DEPARTMENT OF TRANSPORTATION

COBB COUNTY STATE OF GEORGIA 1832

DETAIL 401F
LEFT TURN LANE